


www.evotech-performance.com
Yamaha MT-09
Pillion Peg Removal Kit


## **Installation Instructions**




## Kit Contents PRN015427


- (A) 1 x Left Hand Plate
- **B** 1 x Right Hand Plate
- © 2 x M8 x 25mm Button Head
- D 2 x M8 x 45mm Button Head






















































It is recommended that periodic inspections are made to ensure that all bolts are tightend to the specified torque settings.

Should the bike be involved in an accident a thorough inspection should be made and any components that have taken an impact, no matter how small, be replaced





www.evotech-performance.com